

Construction, Maintenance, and Monitoring of a Geo-timbergrid Structure



Original Headwall







Slopework completed Two benches separating 3, (80%) slopes Gabion toe-support







